In-Production Photo Report for

Lake Charter Township Fire Department, MI

Job# 44699 : PWO# 34564229

Status as of September 03, 2026

In this report your cab completed the paint process, the frame build began (in TN), the pump house remained staged, and the body completed the paint process. In the next report your cab may remain staged to begin initial assembly, the frame build may continue, the pump house may be painted then staged to continue initial assembly, and the body may be staged to begin initial assembly.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT FIRE APPARATUS



DSC06216



DSC06217



DSC06220



DSC09000



DSC09001



DSC09002



DSC09003



DSC09004



DSC06035



DSC06036



DSC06037



DSC06038



DSC06039



DSC06111



DSC06112



DSC06113



DSC06114



DSC06115

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company