# In-Production Photo Report for

## Town of Minocqua Fire Department, WI

## Job# 45349 : PWO# 35074263

Status as of July 31, 2026

In this report your chassis remained staged, the pump house continued initial assembly, and the tank completed the paint process. In the next report the chassis may remain staged to begin preparations for fire and emergency use, the pump house may be painted then staged to continue initial assembly, and the tank may remain staged.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT FIRE APPARATUS




DSC06463




DSC06464



DSC06465



DSC06466




DSC06467




DSC06006



DSC06007



DSC06008



DSC06009



DSC06010




DSC06188




DSC06189



DSC06190



DSC06191



DSC06192

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company