In-Production Photo Report for

Lake Charter Township Fire Department, MI

Job# 44699 : PWO# 34564229

Status as of August 28, 2026

In this report your cab continued through paint, the pump house remained staged, and the body began the paint process. In the next report your cab may continue the paint process, the pump house may be painted then staged to continue initial assembly, and the body may continue through paint.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT FIRE APPARATUS



DSC06367



DSC06368



DSC06369



DSC06370



DSC06371



DSC06010



DSC06011



DSC06012



DSC06013



DSC06014



DSC06462



DSC06463



DSC06464



DSC06466

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company