In-Production Photo Report for

Spencer Fire Department, IA

Job# 42761


Status as of September 03, 2026

In this report your cab was merged with the frame, the pump house was queued for installation, and the body completed the paint process. In the next report the pump house may be merged with the chassis while the body may begin initial assembly.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT FIRE APPARATUS



DSC01313



DSC01314



DSC01315



DSC01316




DSC01317



DSC01318



DSC01319



DSC01320




DSC01321



DSC01322



DSC01323



DSC01281




DSC01282



DSC01283



DSC01284



DSC04417



DSC04418



DSC04419



DSC04420



DSC04421

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company