In-Production Photo Report for

Manchester Fire and Rescue, IA

Job# 44246 : PWO# 34262770


Status as of August 14, 2026

In this report chassis prep continue, the pump house continued initial assembly, and the body completed initial assembly. In the next report the chassis may continue preparations, the pump house may complete initial assembly, and the body may remain staged.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT FIRE APPARATUS



DSC06429



DSC06430




DSC06431



DSC06432




DSC06433



DSC06255



DSC06256




DSC06257



DSC06258



DSC06259



DSC06360



DSC06361



DSC06362



DSC06363



DSC06364

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company