
In-Production Photo Report for

Spencer Fire Department, IA

Job# 42761

Status as of July 24, 2026


In this report your cab was staged to continue the paint process while the pump house structure was fabricated. In the next report your cab may continue through paint while the pump house structure may remain staged.



Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT · FIRE · APPARATUS



DSC03342



DSC03343



DSC03344



DSC03345



DSC04397



DSC04398

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company