In-Production Photo Report for

Manchester Fire and Rescue, IA

Job# 44246 : PWO# 34262770


Status as of August 21, 2026

In this report the chassis continued preparations for fire and emergency use, the pump house completed initial assembly and began testing, and the body completed remained staged. In the next report chassis prep may continue while the pump house and the body may be staged.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT · FIRE · APPARATUS
F R A



DSC06422



DSC06423




DSC06424



DSC06425



DSC06426



DSC06060



DSC06061



DSC06062



DSC06063



DSC06064



DSC06115



DSC06116



DSC06117



DSC06118



DSC06119

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company