In-Production Photo Report for

Spencer Fire Department, IA

Job# 42761


Status as of August 14, 2026

In this report your cab completed the paint process, the pump house was unavailable (in paint booth), and the body completed fabrication and began the paint process with metal finishing. In the next report your cab may be staged to begin initial assembly, the pump house may continue initial assembly, and the body may continue through paint.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT FIRE APPARATUS



DSC02664



DSC02665



DSC02666



DSC02667



DSC02668



DSC02781



DSC02782



DSC02783



DSC02784



DSC02785

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company