In-Production Photo Report for

Manchester Fire and Rescue, IA

Job# 44246 : PWO# 34262770


Status as of July 24, 2026

In this report your pump house continued initial assembly while the body completed fabrication and began the paint process. In the next report your pump house may be painted then staged to continue initial assembly while the body may continue through paint.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT · FIRE · APPARATUS
F R A



DSC06403



DSC06404




DSC06405



DSC06406



DSC06407



DSC06388



DSC06389



DSC06390



DSC06391



DSC06392

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company