In-Production Photo Report for

Sauble – Elk Eden Fire Department, MI

Job# 42818 : PWO# 33290205

Status as of September 03, 2026

In this report your commercial chassis arrived and was staged, the pump was staged (awaiting parts), and the body began fabrication. In the next report your commercial chassis may be staged, the pump may continue the assembly process, and the body may complete fabrication and begin the paint process.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT · FIRE · APPARATUS
F R A



DSC06060



DSC06061



DSC06062



DSC06063



DSC06064



DSC06623



DSC06624



DSC06393



DSC06394



DSC06395



DSC06396



DSC06397

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company