In-Production Photo Report for

Manchester Fire and Rescue, IA

Job# 44246 : PWO# 34262770


Status as of July 31, 2026

In this report your commercial chassis arrived and was staged, the pump house continued initial assembly, and the body completed the paint process. In the next report your commercial chassis may remain staged to begin preparations for fire and emergency use, the pump house may be painted then staged to continue initial assembly, and the body may remain staged.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT · FIRE · APPARATUS
F R A



DSC06468



DSC06469



DSC06470



DSC06471




DSC06472



DSC06473



DSC06474



DSC06036



DSC06037



DSC06038



DSC06039



DSC06040



DSC06133



DSC06134



DSC06135



DSC06136



DSC06137

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company