In-Production Photo Report for

Lake Charter Township Fire Department, MI

Job# 44699 : PWO# 34564229

Status as of August 21, 2026

In this report your cab completed fabrication and was staged to begin the paint process in metal finishing, the pump house was staged, and the body completed the fabrication process. In the next report your cab may continue through paint, the pump house may be painted then staged to continue initial assembly, and the body may be staged to begin the paint process.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT · FIRE · APPARATUS



DSC06271



DSC06272



DSC06273



DSC06274



DSC06275



DSC06010



DSC06011



DSC06012



DSC06013



DSC06014



DSC06196



DSC06197



DSC06198



DSC06199



DSC06200

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company